

Project Resources Inc.

Property Access Checklist


Property Address: \$\(2\) \(5 \) \(0
Property Owner:	Property ID: (CCC)				ON:/	
Property Owner: Zame Property Renter:	Property Address: 3415 Steele St		∐ WORI	K COMPELTED	ON://	
Property Owner: Zone Property Renter: Home Phone: Superior Fax: Cell/Pager: Additional Information: Fax: Cell/Pager: Fax: Cell/Pager: Fax: Cell/Pager: Fax: Cell/Pager: Fax: Cell/Pager: Fax: Cell/Pager: Fax: Fax: Fax: Cell/Pager: Fax: Cell/Pager: Fax:						
Mailing Address: Home Phone: Fax: Cell/Pager: Additional Information:	T		Property R	lenter:	-	
Home Phone: > 0 } S 9 0 1 Additional Information:	<u> </u>		Home Pho	ıe:		
Home Phone: > 0 } S 9 0 1 Additional Information:	3415 5+2010 5	+-	Fax:			
Fax: Cell/Pager: Sent:	74.7 =	·	Cell/Pager			
Fax: Cell/Pager: Sent: 3/10/04 By: A To me S Access Agreement Signed: 4/14/04 By: Restoration Agreement Signed: 4/14/04 By: Topsoil Sampling (if applicable)	Home Phone: 3 03 3 88 9	Cii	Additional	Information:		
Notification Letter Sent: 3 / (0 / 0 4) By: A. Ta me Signed: \(\frac{1}{2} \) \(\frac{1}{2} \) By: \(\frac{1}{2} \) \(\frac{1}{2} \) By: \(\frac{1}{2} \) B						
Notification Letter Sent: 3 / (0 / 0 4) By: A. Ta me Signed: \(\frac{1}{2} \) \(\frac{1}{2} \) By: \(\frac{1}{2} \) \(\frac{1}{2} \) By: \(\frac{1}{2} \) B	Cell/Pager:				,	
Access Agreement Signed: \(\frac{1}{1} \frac{1}{2} \frac{1}{2			<u> </u>	· · · · · · · · · · · · · · · · · · ·		
Access Agreement Signed: \(\frac{1}{1} \frac{1}{2} \frac{1}{2	Notification Letter	Sent: 3	110,04	By: A To	me c	
□ Restoration Agreement Signed: 4/14/C4 By: □ Topsoil Sampling (if applicable) _/_/		Signed: 7	19104	By: Rey men	SIEIRGING F	zowera.
□ Topsoil Sampling (if applicable) _ / _ /					7	•
□ Disposal Sampling (if applicable)//						
Utility Clearance Called: _ / _ / _ By: Video/Photos (Before) On: _ / _ / _ By: Video/Photos (During) On: _ / _ / _ By: Video/Photos (After) On: _ / _ / _ By: Video/Photos (30-Day) On: _ / _ / _ By: Property Completion Agreement Signed: _ / _ / _ By: Final Report Issued: _ / _ / _ By: Air Monitoring (as applicable) Community Crew On: _ / _ / _ By: Results:		/_	_/	Ву:		
Video/Photos (Before)	Garden Sampling (if applicable)	/_	_/	Ву:		
□ Video/Photos (During) On:// By: □ Video/Photos (After) On:// By: □ Video/Photos (30-Day) On:// By: □ Property Completion Agreement Signed://_ By: □ Final Report Issued://_ By: Air Monitoring (as applicable) □ Community □ Crew On://_ By: Results: □ Community □ Crew On://_ By: Results:	Utility Clearance	Called:	/_/_	By:		
□ Video/Photos (After) On: _ / _ / _ By: □ Video/Photos (30-Day) On: _ / _ / _ By: □ Property Completion Agreement Signed: _ / _ / By: □ Final Report Issued: _ / _ / By: Air Monitoring (as applicable) □ Community □ Crew On: _ / _ / _ By: Results: □ Community □ Crew On: _ / _ / _ By: Results:		On: 4/	14/04	Ву:		
□ Video/Photos (30-Day) On:// By: □ Property Completion Agreement Signed://_ By: □ Winal Report Issued://_ By: Air Monitoring (as applicable) □ Community □ Crew On:// By: Results: □ Community □ Crew On:// By: Results:	☐ Video/Photos (During)	On:/	′	Ву:		
□ Property Completion Agreement Signed:// By: □ Final Report Issued:// By: Air Monitoring (as applicable) □ Community □ Crew On:// By: Results: □ Community □ Crew On:// By: Results:	☐ Video/Photos (After)	On:/	'	Ву:		•
Final Report Issued:// By: Air Monitoring (as applicable)	☐ Video/Photos (30-Day)	On:/	/	Ву:		
Air Monitoring (as applicable) Community Crew On:// By: Results: Community Crew On:// By: Results:	☐ Property Completion Agreement	Signed:		Ву:		
Community Crew On:// By: Results: Community Crew On:// By: Results:	☐ Final Report	Issued:	<u>/_/_</u>	Ву:		
Community Crew On:// By: Results: Community Crew On:// By: Results:	Air Monitoring (see soutiesble)					
Results: Community Crew On:// By: Results:		1 1	By:			
Results:			. 			
Results:						
		<u>//</u>	By:			
	Results:					
Community Crew On:/ By:	Community Crew On:	//_	By:			
Results:	Results:					

.....

Property Completion Agreement

This agreement documents the completion of remedial activities performed on my property. My signature will designate that I am satisfied with the restoration of my property, and that no items are in questions, now, or at any time in the future, except those items listed below, if any.

Property ID: (<u> </u>
Property Address: 3415 Steple 5+.		
Owner: Raymond & Ekanor Romero		
Phone: 303 38X 9011		
Sur Gir		
Restoration Items in Question:		
Item:		
ttem.		
Item:		
Item:		
Item:		
Item:		
<u>.</u>		
Item:		
		1
Additional Comments:		
he-set back fence posts-	·	
'		
	·	
·		
Tagree restoration is completed, except as noted		
I do not agree restoration is completed .	·	
I agree that the sprinkler system is working properly following reinstallation by contractor		
Raymond Roman	amy James	8/12/04
Owner's Signature Date	Contractor's Signature	Date '



Real Property Records

Date last updated: Friday, April 02, 2004

® Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

Link to property tax information for this property

Link to property sales information for this neighborhood

Link to property sales information for all Denver neighborhoods

PROPERTY INFORMATION

Property Type: Residential Parcel: 0225128008000

Name and Address Information Legal Description

ROMERO, RAYMOND R & ELEANOR R L 19 & S1/2 OF L 20 EXC REAR 8

3415 STEELE ST FT TO CITY BLK 18 MCKEES ADD

DENVER, CO 80205 RESIDENTIAL

Property Address: Tax District

3415 STEELE ST DENV

Assessment Information

	Actual	Assessed	Exempt	Taxable
Current Year				
Land	18100	1440		
Improvements	155700	12390		
Total	173800	13830	0	13830
Prior Year				
Land	15900	1460		
Improvements	113200	10360		
Total	129100	11820	0	11820

Style: One Story Reception No.: JT00086304

Year Built: 1937 Recording Date: 07/03/97
Building Sqr. Foot: 859 Document Type: Warranty

Bedrooms: 2 Sale Price: 81650
Baths Full/Half: 1/0 Mill Levy: 64.162

Basement/Finished: 859/859

Lot Size: 4,650
Zoning: R2

1600

West hower harry

Х

<> Inq New Update Test Cancel Reset Exit Ticket # 0000416644-000 has been queued! 07/19/04 01:54:16 PM NEW INSERT

Ticket 0000416644 Date 07/19/2004 Time 01:51PM

Oper **JWL966882746**

Rev 000 NEW GRID

Chan WEB

Old Tkt 0000416644 Date 07/19/2004 Time 01:51FM Oper JWL966882746

Phone 303-487-0377 Ext

Caller JASON LYNCH

Email JLYNCH@PROJECTRESOURCESING.COM

Company PROJECT RESOURCES

Fax 303-295-0990

Address 10 E 55TH AVE

City **DENVER**

State CO Zip 80216

Alternate Contact TODD MYERS

Phone 3034870377

Ext

Done for corps of engineers / EPA

Work type SOIL EXCAVATION TO A DEPTH OF 12 INCHES F

Explosives N Boring N

Meet time requested N

St CO Cnty DENVER

Place **DENVER**

Addr From 3415

Street STEELE STREET

Nearest Intersecting Street

Latitude

Longitude

Location ENTIRE RESIDENTIAL PROPERTY FROM THE CURB ONTO THE PROPERTY AT THE ADDRESS LISTED - SOIL EXCAVATION TO A DEPTH OF 12 INCHES.

The locate will be completed between 07/19/04 01:54:17 PM and the end of the day 07/21/2004

Grids (T/R/S) 03S068W25NE 03S068W25NW

Members 360nt3 Atct01 CMSND00 CMSND14 PCNDU0 PSND14 QLNCND00 QLNCND14 WCG01

Members - these will be notified by the center

PSND14 XCEL ENERGY---APPT FILE

XCEL ENGY--APPT SCHEDULE-- UQ

CMSND00

COMCAST - NORTH DENVER
COMCAST - NORTH DENVER

COMCAST - NORTH DENVER COMCAST - NORTH DENVER

http://unccb.uncc.org/ocars/apps/Web TE.asp

PCNDU0	XCEL ENERGY-NORTH DENVER	XCEL ENERGY-NORTH DENVER
PCNDU0	XCEL ENERGY-NORTH DENVER	XCEL ENERGY-NORTH DENVER
PCNDU0	XCEL ENERGY-NORTH DENVER	XCEL ENERGY-NORTH DENVER
PSND14	XCEL ENERGYAPPT FILE	XCEL ENGYAPPT SCHEDULE UQ
QLNCND14	QWEST LOCAL NETWORKAPPT. SCHED.	QWEST LOCAL NETWORK
QLNCND14	QWEST LOCAL NETWORKAPPT. SCHED.	QWEST LOCAL NETWORK
WCG01	WILTEL COMMUNICATIONS LLC	WILTEL COMMUNICATION
QLNCND00	QWEST LOCAL NETWORK	QWEST LOCAL NETWORK (UQ)
360NT3	360 NETWORK-TOUCH AMERICA	360 NETWORK-TOUCH AMERICA
QLNCND00	QWEST LOCAL NETWORK	QWEST LOCAL NETWORK (UQ)
CMSND14	COMCAST-APPT. SCHED.	COMCAST-CATV/UQ
PSND14	XCEL ENERGYAPPT FILE	XCEL ENGYAPPT SCHEDULE UQ
CMSND14	COMCAST-APPT. SCHED.	COMCAST-CATV/UQ
ATCT01	AT&T	AT&T

TIER2 MEMBERS - you must notify these members yourself

DTEO01	DENVER TRAFFIC ENGINEERING OPERATIONS	DNVR TRAFFIC ENG OPERAT.	720-865-4001
DNVH20	DENVER WATER DEPARTMENT	DENVER WATER DEPT	303-628-6666
WWMG01	WASTEWATER MANAGEMENT DIVISION	WASTEWATER MGMT DIVISION	303-446-3744
DNVPR1	DENVER PARKS AND RECREATION	DENVER PARKS & REC.	303-458-4839





U.S. Environmental Protection Agency Vasquez Boulevard I/70 Superfund Site Replacement Certificate

Property Owner	Raymond & Eleanor Romero		
Property Address	3415 Steele St.		
Property Identification Number	1600		

Material Removed	Quantity	Unit Price	Replacement Value
Flower bed area (square feet)	144	\$ 2.50	\$360.00
Itemized plants		\$7.00	\$
Itemized shrubs/bushes	5	\$12.00	\$60.00
Total			\$420.00

The acceptance of the replacement certificate and the signature below is full acknowledgement by the property owner that this is a fair and reasonable compensation for plant materials removed during remediation activities, but not planted or installed by the government or it's contractors.

The total amount of $\frac{420.00}{100}$ has been received by the owner in the form of a replacement certificate, $\frac{413736}{100}$, to be utilized at Paulino's Gardens, 6300 N. Broadway, Denver, CO 80216.

Property Owner's Signature

Date

Contractor's Signature

Date

Restoration Agreement

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID: 1600	· ·
Property Address: 3415 Step1e	5+
Owner: Raymond / Elegnor	izomero
Phone: 303 388 9011	

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

Item:
-711 Statues in yard
Item:
F199 POIR in Front yard
1 1083151: ' /
Plastic border around beds
Item:
Gills and lawn furniture in back
Item:
Dogard dog house
Item:
All tous and equipment in back
Item:
Topper and other mise. items along
them: back garage
1 2000/ WILL HOPPELI
May need help with topper;



· Project Resources Inc.

Items To Be Removed By Contractor During Remediation And Not Replaced (Use additional sheets as necessary)

Tiles in Small area in front ye item: See Swetch Tiles by back garage tem: tem:								•
item: Tiles by back garage item: tem: tem: tem: tem: tem: tem: tem:	item:		·					
item: Tiles by back garage item: tem: tem: tem: tem: tem: tem: tem:	Ti	120	$i \sim 6$	Mell	5124	i	for	
item: Tiles by back garage item: tem: tem: tem: tem: tem: tem: tem:	Item:		1 - 2	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				- /
tem:		500		1404		•		
tem:	item:			<u> </u>				
tem:	<u></u>	100	h	back		000		}
tem:	Item:		y -		· 94.	47		
tem: tem: tem: tem: tem: tem: tem: tem:			ŕ		•			1
tem: tem: tem: tem: tem: tem: tem: tem: tem:	Item:		<u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>					
tem: tem: tem: tem: tem: tem: tem: tem: tem:								
tem: tem: tem: tem: tem: tem: tem:	Item:						·····	
tem: tem: tem: tem: tem: tem: tem:							•	1
tem: em: em: em:	item:							
tem: em: em: em:	٠							
em: em: em:	item:			 				
em: em: em:								1
em: em:	item:	——————————————————————————————————————						
em: em:								
em:	ltem:		<u></u>			 		
em:					•			
em:	tem:							
em:							•	ı
em:	tern:							
em:	•							
em:	tern:							
		:						
em:	tem:	: '						
em:			•	•				1
	tem:						······································	



Project Resources Inc.

Items To Be Removed By Contractor During Remediation And Replaced (Use additional sheets as necessary)

item:	
Item:	Wood Morders around beds
Item:	Pry fence taken dow 1 -
	Note that fence in front
Item:	You can un-bult and
lan-	/ Car, and
item:	Sid it out of the ground
item:	
-	- 1- thes line and poles
item:	
item:	
ltém:	
item:	
84	
ttem:	
item:	
	· ·
ltem:	
item:	
· · · · · · · · · · · · · · · · · · ·	
item:	· · · · · · · · · · · · · · · · · · ·

Landscape Inventory (Use additional sheets as necessary)

Item	Quantity	Unit	Description/Explanation
Total Area Of Property To Be Excavated	3727	Square Feet	·
Number of trees > 2 inch trunk diameter	1		
Number of trees < 2 inch trunk diameter	f		·
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc. Attach a sketch of the sprinkler layout.	N/A		Zones://f Heads://f Control Vaives://f
Number of and total size of all gardens / flower beds.	# Of Beds:	:	Ft ² Of Beds:
Attach a sketch of relative sizes and locations.	# Of Gardens:		Ft ² Of Gardens:

Project Resources Inc.

Item	Quantity	Unit	Description/Explanation
Agreed upon value of plant materials not to be replaced by contractor. Some this value will be used to issue a plant voucher to the property owner.	Total # Of Beds:	\$	Total Ft ² Of Beds To Be Replaced With Certificate: 144 Ft 105 CC Se Bushes
Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed. Include a sketch of were each plant will be piaced by the contractor.	NA	Each	Only Use For Plants That Are Being Saved and Replanted
Agreed upon area of property to be replaced with grass sod. Include a sketch of the area(s) to be replaced with grass sod.	2136	SF	Total Ft ² Of Sod To Be Laid:
Area of City or County property to be landscaped per their requirements. Include a sketch of the area (s)	Total Fr ² :	SF	Sod:/A Brown Mulch:/A Red Mulch: 6 4 4
Agreed upon area of property to be replaced with mulch.	Total Fr Of Mulch:	SF	Red:

螁

· Project Resources Inc.

Item	Quantity	Unit	Description/Explanation
Agreed upon area to be replaced rock.	Total Ft ² Of Rock:	SF	Large: 655 Medium: 4 Small (pea gravel): 4 Driveway Gravel: 138
Agreed upon area to be replaced with no groundcover.	Total Ft ² With No Groundcover: 4 4 4		

Additional Comments / Instructions:

Do not dig small area

in back yard noted

on map.

Use existing wood borders

for areas that they currently

exist

Additional Comments / Inst	nictions Continued.	
Additional Comments / Inst	iuciiona Continucu.	
•		
	i	
·		
	•	
		-
<u>.</u>		
-		•
-		
	·	
	- most interior formelatic	on walls and nossible
Check the box if Owner does not want PRI to doo pre-existing damage. By checking this box PRI is n	ot responsible for any	damage done to the
interior of house, including foundation cracks or fissure	s. ·	
·	1 agree	☐ I do not agree
☑ I agree ☐ I do not agree	~ ~ -8,	
•	- 4	
Ray Parce	Jon Lun	<i>4/13/04</i>

Consent For Access To Property

RIGHT OF ENTRY TO PREMISES

Grantor (the property owner) consents to and authorizes the United States Environmental Protection Agency (EPA) or its authorized representatives, collectively the Grantee, to enter and perform certain environmental response activities upon the following described premises:

Owner's Name:	
	Phone:
Raymond R & Eleanor R Romero	303-388-9011

Addresses of Properties covered by	Address: 3415 Steele St
	Address:
	Address:
this Agreement:	Address:
	Address:

PURPOSE OF RESPONSE ACTIVITIES

The EPA is requesting access to collect soil samples and remove soil that contains elevated concentrations of arsenic and/or lead and may pose a health hazard. The soil will be removed and the excavated area(s) will be replaced with clean materials and restored. This work is being performed under the Vasquez Boulevard/I-70 Superfund Site remediation program.

An EPA representative will contact the Grantor in-person to discuss the work to be performed, the Grantor will have an opportunity to review and approve the planned soil removal, and restoration work before it begins. Once the work is finished, the Grantor will be asked to review the work and confirm that it is complete and meets with the Grantor's approval. Upon completion, the Grantor will receive written documentation from EPA that the property has been remediated.

ENVIRONMENTAL RESPONSE ACTIONS

By signing this Access Agreement, the Grantor is granting the EPA, its employees, contractors and subcontractors the right to enter the property, at all reasonable times and with prior notice, for the sole purpose of performing the work. This access shall remain in effect until the work has been satisfactorily completed. The Grantor also agrees to:

Page 1 of 2

D-3-1


- Remove obstructions including boats, trailers, vehicles, playscape items, wood piles, dog houses, etc;
- Remove flower bulbs or plants that the Grantor or the Grantor's tenant may wish to save;
- Water and maintain replacement vegetation, including fertilizer application, as necessary subsequent to an initial watering period by EPA, unless watering is restricted by Denver Water Board;
- Abide by health and safety guidance provided by EPA;
- If the property is rented, assist EPA in obtaining tenant approval for access to the property to perform the work if EPA is unable to obtain such access; and
- Allow videotaping and/or photography of the property including exterior and interior areas of buildings.

AGREEMENT NOT TO INTERFERE

The Grantor agrees not to interfere or tamper with any of the activities or work done, or the equipment used to perform the activities, or to undertake any actions regarding the use of said property which would tend to endanger the health or welfare of the Grantees or the environment, or to allow others to use the property in such a manner.

Should you have any questions about this program, please contact the VB/I-70 Command Center at (303) 487-0377.

I grant access to my proper	ties-	I do not grant access to m	y-properties
<u>Roymons Rhomers</u> Signature	- 4/9/04 Date	Eleanor Romero Signature	4/9/6 C
☐ I would like to be present d	uring any sampling t	hat is required.	-





Far Far .lwa

USEPA-VB/1-70 Project Site attn. Victor Ketellapper 10 East 55th avenue Denver, Co 80216

80216÷1769

Antalamatan Adama Mantalatan Adamata

TARGET SHEET

EPA REGION VIII SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1033915

	DOCOMENT NOMBER. 100010
SI	TE NAME: VASQUEZ BLVD AND 170
DO	OCUMENT DATE: 08-12-2004
Di	DOCUMENT NOT SCANNED ue to one of the following reasons:
	PHOTOGRAPHS
	3-DIMENSIONAL
	OVERSIZED
V	AUDIO/VISUAL
	PERMANENTLY BOUND DOCUMENTS
	POOR LEGIBILITY
	OTHER
	NOT AVAILABLE
	TYPES OF DOCUMENTS NOT TO BE SCANNED (Data Packages, Data Validation, Sampling Data, CBI, Chain of Custody)
DC	CUMENT DESCRIPTION:
	DVD OF PROPERTY VIDEO